

CHATHAM COUNTY DEPARTMENT OF BUILDING SAFETY AND REGULATORY SERVICES

FIRE SAFETY INSPECTION DIVISION

YEAR OF: 2006

DATE

3/13/07

APPROVED  
DISAPPROVED

You are hereby notified that this is an Official Order of the County Fire Marshall, stating the defects found to exist in the referenced structure, and further rec that you, as owner, agent or person in charge of structure shall have \_\_\_\_\_ days to complete specified repairs or improvements.

Bus. Phone: 919-3310 Owner: Board of ED. Occupant/Lead:

Name of facility/Address: SOUTHWEST MIDDLE SCHOOL / 6030 CREECH

OCCUPANCY: Business Assembly Storage Educational Day Care Personal Care Home Mercantile Factory Residential Hazardous

SCHOOL

- 1. Number of Exit Doors: MULTIPLE 101-SEC 5
- 2. Blocked:  Locked  OK 101-SEC 5
- 3. Exit Sign: Good  Unsatisfactory  NA 101-SEC 5
- 4. Emergency Lights: Good  Unsatisfactory  NA 101-SEC 5
- 5. Panic Hardware: Good  Unsatisfactory  NA 101-SEC 6
- 6. Self-Closing Device: Good  Unsatisfactory  NA
- 7. Fire Alarm: Yes  No  NA NFPA 72
- 8. Smoke/Heat Detectors: Yes  No  NA NFPA 72
- 9. Sprinkler System: Yes  No  NA NFPA 13
- 10. Standpipes: Yes  No  NA NFPA 19
- 11. Number of Fire Extinguishers: MULTIPLE
- Proper Type? Yes  No  NA NFPA 10
- Inspected/Charged: Yes  No  NA NFPA 10
- 12. Fixed Hood System: Yes  No  NA NFPA 96
- 13. Date of Last Service: DEC/06 REQUIRED EVERY 6 MONTHS
- 14. Electrical: Good  Fair  Unsatisfactory  NFPA 70
- 15. Overloaded sockets/outlets: Yes  No  NFPA 70
- 16. Missing electrical covers: Yes  No  NFPA 70
- 17. Other (explain):
- 18. Excessive Storage of Combustibles: Yes  No  NFPA 30

List Details:

- 1- FIRE PANEL IN TROUBLE
- 2- EXIT LIGHT OUT IN GYM
- 3- EDC NEEDS CAP.
- 4. PARTIAL SPROKLER SYSTEM PROTECTS GYM AND LUNCH RM.
- 5. SUPPRESSION SYSTEM IN KITCHEN NOT REPORTING THRU FIRE PANEL

The signature below of Owner, Occupant, Agent, signifies inspection was made.

Owner/Occupant/Agent Signature: [Signature]

Chatham County Fire Marshall: [Signature]